

523/21-22

Schedule XLV-Form No. 134

310721 95412 3rd

Prima 221 एनए रीमा है LOYS (HHAIGY) SC
(चंदावर्तिन अंतरिक्ष अर्थ)

DIVISION

310721

SUB-DIVISION

310721

MEASUREMENT BOOK

9th 4th 5th 6th 7th 8th 9th 10th 11th

3rd year maintenance

13

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Maintenance of road from Sikatiya Baky To 10 to 1.45 under 111157-2					
Agency- Ajay Kumar Dubey					
Agreement NO- 1653D/2020-21					
Actual date of completion- 25/02/2024					
3rd Year Maintenance 26/02/2023					
Period 25/02/2024					

① Restoration of Raincuts

1	X	6.25	X	1.20	X	0.30	=	2.25 m ³
2	X	7.00	X	1.10	X	0.30	=	4.62 m ³
1	X	5.75	X	1.15	X	0.25	=	1.64 m ³
2	X	9.00	X	1.10	X	0.25	=	4.95 m ³
1	X	8.10	X	1.20	X	0.30	=	2.92 m ³
1	X	6.00	X	0.90	X	0.25	=	1.35 m ³
3	X	8.00	X	1.15	X	0.30	=	8.28 m ³
1	X	7.50	X	1.20	X	0.30	=	2.70 m ³
1	X	5.00	X	0.90	X	0.25	=	1.12 m ³
2	X	6.50	X	1.10	X	0.30	=	4.29 m ³
1	X	7.10	X	1.20	X	0.30	=	2.56 m ³
2	X	8.15	X	1.25	X	0.30	=	6.11 m ³
								42.79 m ³

② Maintenance of earthen Shoulder

1	X	8.50	X	1.20	=	10.20 m ³
2	X	7.00	X	1.25	=	17.50 m ³
2	X	6.50	X	1.28	=	16.64 m ³
						44.34 m ³

Continuation

Abstract of cost

16

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Raincuts					
Q-VTNB/13 ① =		42.79H			
e h		406.82/H			17408=0
② Maintenance of earthen shoulder					
Q-VTNB/13 ② =		372.06H			
e h		61.70/H			22956=0
③ Maintenance of bitumen surf.					
(i) Repair to pot holes					
Q-VTNB/14 ③ =		42.46H			
e h		430.03/H			18259=0
(ii) Patch repair:					
Q-VTNB/14 ③ =		42.46H			
e h		286.32/H			12157=0
④ Maintenance of slab culvert					
Q-VTNB/15 ④ =		1 Nos			
e h		2329.21/each			2329=0
⑤ cutting of branches of trees					
Q-VTNB/15 ⑤ =		2 km			
e h		109=74/each			219=0
⑥ Trimming of grass					
Q-VTNB/15 ⑤ =		678.0H			
e h		2.24/H			1519=0
⑦ Planting of trees by the road side					
					74847=0

Continuation

Scanned by CamScanner