

2nd yr winter

37

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① N/PW		Prasety road to Haripura besides			
		Kulki Purji tank in Panapura			
② N/A	Rambalak Ray				
	Tulsi Kharani, Panapura				
	Muzaffarpur				
③ Agar	-	Survey & Exp (S&E) - 31/10/2019 - 22/11/2019			
④ Actual date of compilation		20-01-2022			
⑤ Restoration of embankment					
	Length	2.25			
	Width	2.10	1.20	0.45	48.6 m <sup>3</sup>

⑥ Maintenance of earthy shoulder				
	Length	2.25		
	Width	0.90	1.0	2.70 m
	Depth	0.05	2	2.25 m <sup>2</sup>

⑦ Repair to pot holes				
	Length	1.4	2	9.8 m
	Width	1.0	2	15.87 m <sup>2</sup>
	Depth	0.9	2	11.88 m <sup>2</sup>
				37.55
				Unit 37.55 m <sup>2</sup>

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Restoration of embankments					
T. emb. P (37) - 48.6 m <sup>3</sup>					
@ Rs 380 = 18,496/-					
2. Maintenance of earthen Shanty					
T. emb. P (38) - 270.0 m <sup>2</sup>					
<del>270.0 m<sup>2</sup></del>					
@ Rs 58 = 15,822/-					
3. Repair to Pot-holes					
T. emb. P (37) - 37.50 m <sup>2</sup>					
@ Rs 245 = 9,218/-					
4. Maintenance of pump pipe					
T. emb. P (38) - 6.0 m					
@ Rs 117 = 670.2/-					
5/8. Reinforcing steel bars					
T. emb. P (38) - 0.92 kgm					
@ Rs 1074 = 989/-					
6/8. Maintenance of roads & King Star.					
T. emb. P (38) - 0.92 kgm					
@ Rs 735 = 676.2/-					
					R 5190/-
Less V.V. as per cent					
Materials					R 46,713/-
(i) Soil 75.6 m <sup>3</sup>					
(ii) Stone Aggr. 1.02 m <sup>3</sup>					
(iii) Mortar 0.09 m <sup>3</sup> M10					
(iv) 24 nos. 100x100x100 mm					
24 nos. Continuation					
SEI record					