

Name of person - Madhish. Bidyalay Akbarpur Bank village
to Mr. Jivan Saha Saha Subat (9)

Schedule XLV-Form No - 134

AKBARPUR BANK

M. N. G. S. J.
~~SC~~ SC

Bismail

PT 482300

SUB-DIVISION

Subat

Ag. No - 74/5.B.D/17-18

MENo - 887

MEASUREMENT BOOK

W. PARVEZ ALAM

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstracts of cost</u>					
① Restoration of rainfalls					
P/77					= 623.61 m ³
					② 358.87 = 44360/-
② Stripping excess soil					
P/77					= 699.50 m ²
Limit					699.50 = 693.56 m ²
					③ 54.16 = 37560/-
③ Pr. Patch Repair Pot-holes					
P/77					= 96.74 m ²
Limit					= 96.33 m ²
					④ 112.45 = 10832/-
④ Pr. Patch Repair of Bit Surface					
P/78					= 99.20 m ²
Limit					= 96.33 m ²
					⑤ 100.92 = 9722/-
⑤ Maintenance of H.P. Culvert					
P/78					= 04 Nos
					⑥ 1067.89 = 4272/-

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑥ Maintenance of Slab Culvert P/78		= 04		Nos	
	@	2200.02	=	8800/-	
⑦ Maintenance of Road Signs P/79		= KM = 2.08			
	@	1025.45	=	2108/-	
⑧ Maintenance of 200m/KM How P/79		KM = 2.06			
	@	575.57	=	1183/-	
⑨ White washing of Parapet Wall P/79		83.20 m ²			
	@	15.55	=	1294/-	
				<u>12013/-</u>	
				(-) 12013/-	
				<u>108118/-</u>	
<u>Materials</u>					
① Earth work	2			123.61 m ³	
② chips				3.60 m ³	
③ dust				1.1 m ³	

[Signature]
08/08/2014