


INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:-	EE RWD, Beland (W.)		
Name of Block/Road:-	Bairgania, L037 -T02 se piprahi Sultan		
A. For Road			
1. Damage Location/Chainage:-	0.150KM, 0.230KM, 0.300km		
2. Damage Length	0.134 km		
3. Nature of Damage (Length Wise):-	(i) Breach:-	✓	
	(ii) Crust Damage		
	(iii) Only Flank Damage:-		
Whether traffic fully/Partialiy Obstructed:-	Fully obstructed		
4. Details of Restoration:-			
(i) Material Being Used in Restoration:-	Brick bats		
(ii) Equipment/Tools Being Used in Restoration Works:-	Hydraulic Excavator, Tipper, etc		
(iii) Restored Length:-	In Open Area:-	✓, 0.134km	
	IN Habitation Area:-		
(iv) If Restoration work done in Habitation Area Give Reason:-			
B. For Bridge (Size of Bridge/Culvert):-			
(1) Damage Location/ Chainage:-			
(2) No. of Span Damage:-			
(3) Length of Span:-			
(4) Nature of Damage (Pier/ Abuttment/Wing Wall/Approach Road Damage:-			
(5) Details of Restoration:-			
(i) Material Being Used in Restoration:-			
(ii) Equipment/Tools Being Used in Restoration Works:-			
(iii) Restoration Length:-			
Overall Grade of Restoration Work (Satisfactory/Unsatisfactory):- Satisfactory			


 29/12/23
 Signature of Inspector
 (Officer Seal)
 H. M. D. Water Division
 Srinagar