INPSPECTION REPORT FOR MOTORABLE WORK	
ne of PIUs: - 5%. Manoj kumor, works division pupoi.	
ne of Block/Road: Bokhra/coust" of proposed HL RCC Boildge ones damodar River from palitolato Chakauti Rd.	
I OI Road	
Damage location /Chainage :-	
Damage Length: 51m CH 5m	
	i) Breach: 51m
Vature of Damage (Length Wise)	ii) Crust Damage :-
	iii) Only Flank Damage
nether Traffic Fully / Partially obstructed: Fully obstructed	
Details of Restoration :-	
	Brick Bats, Rubbush, Hume pipe
Equipment / Tools Being used in Restoration Work: JCB, Rolle & fractor	
Destared Length	In open Area :- In Habitation Area :-
) If Restoration Work Done in habitation Area give Reason: - NA	
For Bridge (Size of Bridge / Culvert )	
Damage Location / Chainage :-	
No. of Span Damage:-	
Lenth of Span :-	
Nature of Damage ( Pier/Abuttment/ Wing Wall/ Approach Road Damage ):-	
Details of Restoration :-	
Material Being Used in Restoration:-	
) Equipment / Tools Being used in Restoration Work: JCB, Koller & Tracker	
i) Restored Length	
verall Grade of restoration Work (Satisfactory/Unsatisfactory): - Satisfactory	

Signature of Inspector
(Official Seal