

Inspection Report for Flood Damage Work

Date :

1. Name of PIUs :- EE RWD WORKS DIVISION, SUPAUL

2. Name of Block/Road :- KISHANPUR, SUPAUL
LOS8 Ashanpur to Mushari (BKBDP)

A. For Road

1. Damage Location/Chainage : CH - 0 to 880 mtr

2. Damage Length :

3. Nature of Damage : FULL BREACH

4. Details of Restoration Works :

- Material being used in Restoration work : BRICK BATS, LOCAL SAND
- Equipment/Tools being used in Restoration work : JCB, TRACTOR
- Procedure taken up in Restoration work : PLACING OF MATERIAL, COMPACTION
- Restored Length : 880 mtr

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :


4. Details of Restoration Works :

- Material being used in Restoration work :
- Equipment/Tools being used in Restoration work :
- Procedure taken up in Restoration work :
- Restored Length :

JE


AE


EE
Executive Engineer
Rural Work's Department
Work's Division, Supaul


Signature
(Name of Inspector)
Executive Engineer
Rural Works Department
Works Division Udakishung