

Inspection Report for Flood Damage Work

Date :

1. Name of PIUs :- EE RWD WORKS DIVISION SUPAUL

2. Name of Block/Road :- KISHANPUR (SUPAUL)
PARSA YADAV TOLA TO KALMUNTRA (BKBDP)

A. For Road

1. Damage Location/Chainage : 0 TO 520 CH

2. Damage Length : FULL BREACH

3. Nature of Damage :

4. Details of Restoration Works :

- Material being used in Restoration work : BRICK BATS, LOCAL SAND
- Equipment/Tools being used in Restoration work : JCB, TRACTOR
- Procedure taken up in Restoration work : PLACING OF MATERIAL
- Restored Length : 520 MTR COMPACTON

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :


4. Details of Restoration Works :

- Material being used in Restoration work :
- Equipment/Tools being used in Restoration work :
- Procedure taken up in Restoration work :
- Restored Length :

JE


11/11/2024
AE


EE
Executive Engineer
Rural Work's Department
Work's Division, Supaul


Signature
(Name of Inspector)
Executive Engineer
Rural Works Department
Works Division Udakishu