


INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- <u>Ex. Manoj Kumar</u>	
Name of Block / Road :- <u>Bajpatti / Bagilpur Pansyod to Saton Pant</u> <u>Chakra Jabra</u>	
A. For Road	
1. Damage location / Chainage :- <u>165 m.</u>	
2. Damage Length :- <u>165 m</u>	
3. Nature of Damage (Length Wise)	(i) Breach :- <u>165 m</u>
	(ii) Crust Damage :-
	(iii) Only Flank Damage
Whether Traffic Fully / Partially obstructed :- <u>partially obstructed.</u>	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- <u>Brick Bats, Labyrinth & Home Pipe</u>	
(ii) Equipment / Tools Being used in Restoration Work :- <u>JCB, Roller, Tractor</u>	
(iii) Restored Length	In open Area :- <u>165 m.</u>
	In Habitation Area :-
(iv) If Restoration Work Done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge / Culvert)	
(1) Damage Location / Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abutment/ Wing Wall/ Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment / Tools Being used in Restoration Work :- <u>JCB, Roller, tractor</u>	
(iii) Restored Length	
Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :- <u>Satisfactory</u>	


 Signature of Inspector
 (Official Seal)