

# INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Er. Manoj Kumar, Works division, Rupn

Name of Block / Road :- Surand / NH 104 Simyahi more to Simyahi village.

## A. For Road

1. Damage location / Chainage :- ch. → 1100 m, ch. → 1600 m.

2. Damage Length :- 43 m.

3. Nature of Damage ( Length Wise)

(i) Breach :- 43 m.
(ii) Crust Damage :-
(iii) Only Flank Damage

Whether Traffic Fully / Partially obstructed :- Fully obstructed.

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick baddi Rabbish.

(ii) Equipment / Tools Being used in Restoration Work :- JCB, Roller & tractor.

(iii) Restored Length

In open Area :-
In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :- NA

## B. For Bridge (Size of Bridge / Culvert )

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage ( Pier/Abutment/  
Wing Wall/ Approach Road Damage ) :-


(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :- JCB, Roller, tractor.

(iii) Restored Length

Overall Grade of restoration Work ( Satisfactory/Unsatisfactory) :- Satisfactory.

  
14/11/24  
Signature of Inspector  
(Official Seal)