

# Inspection Report for Flood Damage Work

Date :

1. Name of PIUs :- EE RWD WORKS DIVISION, SUPAUL
2. Name of Block/Road :- (KISHANPUR) Tharbitiya to Shiv puri Mushari

## **A. For Road**

1. Damage Location/Chainage : CH:- 800 to 1360
2. Damage Length : 485 mtr
3. Nature of Damage : FULL BREACH
4. Details of Restoration Works :
  - i. Material being used in Restoration work : BRICK BATS, LOCAL SAND
  - ii. Equipment/Tools being used in Restoration work : JCB, TRACTOR
  - iii. Procedure taken up in Restoration work : PLACING MATERIAL, COMPACTION
  - iv. Restored Length : 500 mtr

## **B. For Bridge**


1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration work :
  - ii. Equipment/Tools being used in Restoration work :
  - iii. Procedure taken up in Restoration work :
  - iv. Restored Length :

JE

  
AE



EE  
Executive Engineer  
Rural Work's Department  
Work's Division, Supaul



Signature  
(Name of Inspecting Engineer)  
Executive Engineer  
Rural Works Department  
Works Division Udakishung