

# Inspection Report for Flood Damage Work

Date :

1. Name of PIUs :- EE RWD WORKS DIVISION, SUPAUL

2. Name of Block/Road :- KISHANPUR (SUPAUL)  
NH 57 TO PARSA YADAV TOLA

## **A. For Road**


1. Damage Location/Chainage : 0 TO 890
2. Damage Length : 673 mtr
3. Nature of Damage : FULL BREACH
4. Details of Restoration Works :
  - i. Material being used in Restoration work : BRICK, BATS, LOCAL SAND
  - ii. Equipment/Tools being used in Restoration work : JCB, TRACTOR
  - iii. Procedure taken up in Restoration work : PLACING OF MATERIAL
  - iv. Restored Length : COMPACTION


## **B. For Bridge**

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration work :
  - ii. Equipment/Tools being used in Restoration work :
  - iii. Procedure taken up in Restoration work :
  - iv. Restored Length :

JE

  
AE

  
EE  
**Executive Engineer**  
Rural Work's Department  
Work's Division, Supaul

  
Signature  
(Name of Inspector)  
**Executive Engineer**  
Rural Works Department  
Works Division Udakishungu