

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.E. RWD works Division, Beland	
Name of Block /Road :- Bishampur to Mahindwara road under Ramnoidpur Block	
A. For Road	
1. Damage location /Chainage :- 26.335119; 85.410087	
2. Damage Length :- 0.024 km	
3. Nature of Damage (Length Wise)	(i) Breach :- 0.024 km
	(ii) Crust Damage :-
	(iii) Only Flank Damage
Whether Traffic Fully / Partially obstructed :- Fully obstructed	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- brick bats; Rabbish	
(ii) Equipment / Tools Being used in Restoration Work :- JCB, Tractor, Roller	
(iii) Restored Length	In open Area :- 0.024 km
	In Habitation Area :-
(iv) If Restoration Work Done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge / Culvert)	
(1) Damage Location / Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abutment/ Wing Wall/ Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment / Tools Being used in Restoration Work :-	
(iii) Restored Length	
Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :- Satisfactory	

Signature of Inspector
(Official Seal)
Executive Engineer
Rural Works Department
Works Division, Sheohar