

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Sri Avinash Kumar, EE RWD Sitamarhi

Name of Block / Road :- Tirkaulija to Kharat Jola
under Bathnaha Block

A. For Road

1. Damage location / Chainage :- at chainage - 1220m, lat : 26.6679S, long : - 85.525039

2. Damage Length :- 11.6m

3. Nature of Damage (Length Wise)

(i) Breach :- 11.6m

(ii) Crust Damage :-

(iii) Only Flank Damage :-

Whether Traffic Fully / Partially obstructed :- partially obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick Bath, Robbins

(ii) Equipment / Tools Being used in Restoration Work :- J.C.B, Tractor

(iii) Restored Length

In open Area :-

In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :- N.A

B. For Bridge (Size of Bridge / Culvert)

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/ Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :-

(iii) Restored Length

Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :-

Signature of Inspector
(Official Seal)

1411-24