

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Sri Avinash Kumar, EE RWD Sitamarhi

Name of Block / Road :- Narha Brahmanthan to Musahar
Naya Jola under Bathnaha Block

A. For Road

1. Damage location / Chainage :- chainage 1150-1220, 2415-2430, Lat - 26.669431, 2415-2430, Lat - 26.6677

2. Damage Length :- Total = 213m. Long - 85.59807, Long - 85.59807

3. Nature of Damage (Length Wise) (iii) 3050-3120, Lat - 26.669521, Long - 85.598791

(i) Breach :- 213m.

(ii) Crust Damage :-

(iii) Only Flank Damage

Whether Traffic Fully / Partially obstructed :- Partially obstructed.

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick Bath, Raebrieh

(ii) Equipment / Tools Being used in Restoration Work :- JCB, Tractor

(iii) Restored Length

✓ In open Area :-

In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :- N.A

B. For Bridge (Size of Bridge / Culvert)

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/ Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :-

(iii) Restored Length

Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :-

Signature of Inspector
(Official Seal)

14-11-24