

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Er. Manoj Kumar

Name of Block / Road :- Baypatti / Bachopatti Narkh chook Bazar rd. to Mahuain Pathak hlg

A. For Road

1. Damage location / Chainage :- ch:- 600m, 685m, 820m

2. Damage Length :- 106m

3. Nature of Damage (Length Wise)

(i) Breach :- 106 m
(ii) Crust Damage :-
(iii) Only Flank Damage

Whether Traffic Fully / Partially obstructed :- ~~fully~~ ^{partially} obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick-Bat, Rabbish & Bafropillin-chackon

(ii) Equipment / Tools Being used in Restoration Work :- JCB, Roller, Tractor.

(iii) Restored Length

In open Area :- 106m
In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :-

B. For Bridge (Size of Bridge / Culvert)

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Lenth of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/ Approach Road Damage) :-


(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :- JCB, tractor, Roller

(iii) Restored Length

Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :- Satisfactory


19/11/24
Signature of Inspector
(Official Seal)