INSPECTION REPORT FOR MOTORARIE WORK

Name of PIUs :- QWD 140	TOR MOTORABLE WORK
A CONTRACTOR OF THE PROPERTY O	DIVISION DE LA
A. For Road	when I marking to Dannoan
1. Damage Location/Chainage:- o	
2. Damage Length .	.25 KM, 0.55 KM, 0.85 KM.
3. Nature of Damage (Length Wise)	W,
Be (Bength Wise)	
	(ii) Crust Damage:- 41 ~~
whether traffic fully/Partialiy obstruct	(iii) Only Flank Damage :- N-A
4. Details of Restoration:	ted:- Feerly
The state of the s	
(i) Material Being Used in Restoration	n:- Boichs boots,
(ii) Equipment/Tools Being Used in R	Restoration Works: - 10B, toceating.
(iii) Restored Length	In open Area:- 41000.
	In habitation Area:- N-A
(iv) If Restoration work done in habitation Area give Reason:-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage:-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttmen	ıt/
Wing Wall/Approach Road Damage)	:-
(5) Details of Restoration:-	,
(i) Material Being Used in Restoration	1:-
(ii) Equipment/Tools Being Used in R	estoration Works :-
(iii) Restored Length:-	
1	(S. Linfortamy/I Insatisfactory): Satisfactory
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Satisfactory	
	Juli m
	2 Signature vertitos interar

4. Juman

11/11/2024 6nm Az

Signature of the the Rura Official Septentiment Works Division Phulparas