INSPECTION REPORT FOR MOTORABLE WORK

, ,		
Sehistactory	Overall Grade of Restoration Work (Satisfactory / Unsatisfactory)	Overall Grade of Restora
	In habitation Area:	
	In open Area:-	(iii) Restored length
	(ii) Equipment / Tools being Used in Restoration Works:	(ii) Equipment / Tools be
	n Restoration:	(i) Material Being Used in Restoration:
	37 7	5. Details of Restoration:
37	(Pier / Abutment/Wing wall/Approach Road Damage)	4 Nature of Damage (Pier
	& P	3 Length of Span
	る中	2. No. of Span Damage:-
	inage:	1. Damage Location / Chainage
	idge / Culvert)	B. For Bridge (Size of Bridge / Culvert)
	(iv) if Restoration work done in habitation Area give Reason:-	(iv) if Restoration work do
	In habitation Area:-	
	In open Area:	(iii) Restored length
Smooth wheels	(ii) Equipment / Tools being Used in Restoration Works: Front God londer	(ii) Equipment / Tools bein
Spare Scoresia	Restoration: - Briefly Sady, M/s fige,	(i) Material Being Used in Restoration:
		4. Details of Restoration;
	ily obstructed - Fully obstructed.	whether traffic fully/Partialily obstructed
	(iii) Only Flank Damage	
	(ii) Crust Damage: $\int e^{\cdot o_m}$.	
	wise) (i) Breach:- 14.0m.	3. Nature of Damage (length wise)
	72.0 m	Damage Length:
	age: 01: 3.800/m,	1. Damage Location / Chainage:
		A. For Road
	Pierraly 17 Govindpor to ataryoupur	Name of Block / Road :-
	works Division, Renalgoon.	Name of PIUs :- RWA,

D

thustoning 12.11.21

Signture of Inspector

Frontitive Stangineer

N. D., W. D. Naugechie