


INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Er. Manoj Kumar, Works Division, Purni	
Name of Block / Road :- Sursand / NH 104 Bathuahq Bazar to Korbanna,	
A. For Road	
1. Damage location / Chainage :- ch. → 750 M, ch. → 1100 M, ch. → 1800 M, ch. → 2000 M, ch. 2850 M.	
2. Damage Length :- 193 M.	
3. Nature of Damage (Length Wise)	(i) Breach :- 193 M.
	(ii) Crust Damage :-
	(iii) Only Flank Damage
Whether Traffic Fully / Partially obstructed :- Fully obstructed.	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- Brick Bats, Rubbish.	
(ii) Equipment / Tools Being used in Restoration Work :- JCB, Roller & tractor.	
(iii) Restored Length	In open Area :-
	In Habitation Area :-
(iv) If Restoration Work Done in habitation Area give Reason :- NA	
B. For Bridge (Size of Bridge / Culvert)	
(1) Damage Location / Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abutment/ Wing Wall/ Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment / Tools Being used in Restoration Work :- JCB, Roller & tractor	
(iii) Restored Length	
Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :- Satisfactory.	


14/11/24
Signature of Inspector
(Official Seal)