

## Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road - GAIGHAT / CONS. OF R.C.C H.L BRIDGE FROM JARANG TO LOHBANDRA ROAD TO SURAGHAT

A For Road ☒

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

☒ B For Bridge

1 Damage Location/Chainage - 0m

2 Damage Length - 0.080 km

3 Nature of Damage - Damage due to flood

4 Details of Restoration Works

i material Being used in Restoration Works - BRICK BATS, LOCALSAND, HUME PIPE

ii Equipments/Tools being used in Restoration Works - DUMPER, TRACTOR, JCB, ROLLER.

iii Procedure Taken up in Restoration Works - SPREADING OF BRICK BATS AND LOCAL SAND AND COMPACTING THE SURFACE.

iv Restored length - 0.080 km

Signature of JE/AE/EE

Signature (Name of Inspector)  
Executive Engineer  
RWD Works Division  
Muzaffarpur East-1