

## Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road AURAI / NAYAGAON - GANGULI MADHOPUR ROAD.

A For Road

1 Damage Location/Chainage 2.3 Km

2 Damage Length - 0.045 Km

3 Nature of Damage - DAMAGE DUE TO FLOOD.

4 Details of Restoration Works

- i material Being used in Restoration Works - BRICK BATS AND LOCAL SAND.
- ii Equipments/Tools being used in Restoration Works - TRACTOR, JCB, ROLLER, DUMPER
- iii Procedure Taken up in Restoration Works - SPREADING OF BRICK BATS AND LOCAL SAND AND THEN COMPACTING THE SURFACE
- iv Restored length - 0.039 Km

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

- i material Being used in Restoration Works
- ii Equipments/Tools being used in Restoration Works
- iii Procedure Taken up in Restoration Works
- iv Restored length

Signature of JE/AE/EE

Signature (Name of Inspector)

Executive Engineer  
RWD Works Division  
Muzaffarpur East-1