

Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road Aurai / L056 NH-77 Katujha T010 To Kalyanpur (VR32)

A For Road

1 Damage Location/Chainage 0-200km

2 Damage Length 0.072 km.

3 Nature of Damage Damage due to flood

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Brick bats and local sand
Tractor, JCB, Dumper Roller
Spreading of Bricks bats and
local sand and then \rightarrow Compacting
the Surface.

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

Sham
12/11/24

AE
13/11/24

Signature (Name of Inspector)

YCP
13/11/24
Executive Engineer
RWD Works Division
Muzaffarpur East-1