

Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road — AURA / LOGO-TO8 TO BASI BAIJNATH ALI NAGAR

✓ A For Road

1 Damage Location/Chainage — 2.9 Km

2 Damage Length — 0.014 Km

3 Nature of Damage — DAMAGE DUE TO FLOOD

4 Details of Restoration Works — BRICKS BATS AND LOCAL SAND.

i material Being used in Restoration Works —

ii Equipments/Tools being used in Restoration Works — TRACTOR, JCB, ROLLER, DUMPER.

iii Procedure Taken up in Restoration Works — SPREADING OF BRICK BATS AND

iv Restored length — 0.014 Km LOCAL SAND AND THEN COMPACTING THE SURFACE.

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

Signature (Name of Inspector)

Executive Engineer
RWD Works Division
Muzaffarpur East-1