

Inspection Report for Flood Damage work

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road — AURAT / LOG7-TO4 TO KALYANPUR (VR42)

A For Road 0.600km

1 Damage Location/Chainage

2 Damage Length — 0.012km

3 Nature of Damage — Damage due to flood.

4 Details of Restoration Works —

i material Being used in Restoration Works — BRICK BATS AND LOCAL SAND, HUME PIPE

ii Equipments/Tools being used in Restoration Works — TRACTOR, JCB, DUMPER, ROLLER.

iii Procedure Taken up in Restoration Works — Spreading of Brick BATS AND LOCAL SAND AND THEN COMPACTING THE SURFACES.

iv Restored length 0.012 km

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE
Sham
12/11/24

Signature
12/11/24
AE

Signature (Name of Inspector)
Y. P. S.
13/11/24
Executive Engineer
RWD Works Division
Muzaffarpur East-1