

Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road - KATRA / CONS OF ROAD FROM VARDI TO P.W.D
MAHADALI TOLA MD. KHURSHID HOUSE OF NAGENDR
A For Road PASWAN IN CHAUDALI PANCHAYAT.

1 Damage Location/Chainage 0.70 Km

2 Damage Length - 0.025 km

3 Nature of Damage - DAMAGE DUE TO FLOOD.

4 Details of Restoration Works

i material Being used in Restoration Works - BRICK BATS AND LOCAL SAND.

ii Equipments/Tools being used in Restoration Works - TRACTOR, JCB, ROLLER, DUMPER.

iii Procedure Taken up in Restoration Works - SPREADING OF BRICK BATS AND LOCAL

iv Restored length 0.02050 km SAND AND THEN COMPACTING THE SURFACE

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

Sham
12/11/24

Sham
13/11/24
AE

Signature (Name of Inspector)
Executive Engineer
RWD Works Division
Muzaffarpur East-1

Yp
13/11/24