

Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road - AVRAI / SHAHPUR MDR TO DAKR AMA SIMAN

☒ A For Road 1 km

1 Damage Location/Chainage . 1 km

2 Damage Length - 0.020 km

3 Nature of Damage - DAMAGE DUE TO FLOOD.

4 Details of Restoration Works

i material Being used in Restoration Works - BRICK BATS AND LOCAL SAND.

ii Equipments/Tools being used in Restoration Works - TRACTOR, JCB, DUMPER, ROLLER.

iii Procedure Taken up in Restoration Works - SPREADING OF BRICK BATS AND LOCAL

iv Restored length - 0.17 km SAND AND THEN COMPACTING THE SURFACE

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

Signature (Name of Engineer)

Executive Engineer
RWD Works Division
Muzaffarpur East-1