

Date

## Inspection Report for Flood Damage work

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road - AURAI / RAMPUR PND ROAD TO SAMBHUTA

✓ A For Road 0.8 Km

1 Damage Location/Chainage

2 Damage Length - 0.040 km

3 Nature of Damage - DAMAGE DUE TO FLOOD

4 Details of Restoration Works

i material Being used in Restoration Works - BRICK BATS AND LOCAL SAND.

ii Equipments/Tools being used in Restoration Works - TRACTOR, JCB, DUMPER, ROLLER.

iii Procedure Taken up in Restoration Works - SPREADING OF BRICK BATS AND LOCAL

iv Restored length - 0.035 km SAND AND THEN COMPACTING THE SURFACE.

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

Sham  
13/11/24

13/11/24  
AE

Signature (Name of Engineer)

13/11/24  
Executive Engineer  
RWD Works Division  
Muzaffarpur East-1