

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE, RWD, Works Division, Belsand
Name of Block / Road :- Sitamarhi jila antargat belsand pralchand me maharani asthan saraiya se gothwara hote hue tamha ara mil REO Sadak tak mitti seling, PCC path ka nirman

A. For Road

1. Damage location / Chainage :- 26.422266, 05.423388

2. Damage Length :- 0.176 KM

3. Nature of Damage (Length Wise)

(i) Breach :- 0.176 KM

(ii) Crust Damage :-

(iii) Only Flank Damage

Whether Traffic Fully / Partially obstructed :- Fully obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick Bats, Rabbish

(ii) Equipment / Tools Being used in Restoration Work :- JCB, Tractor, Roller

(iii) Restored Length

In open Area :- 0.176 KM

In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :-

B. For Bridge (Size of Bridge / Culvert)

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/ Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :-

(iii) Restored Length

Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :- Satisfactory

Signature of Inspector
(Officer) Executive Engineer
Rural Works Department
Works Division, Sheohar