

# INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.E. RIND, works Division, Belson

Name of Block / Road :- Hajipur Basant to Tilak Tajpur Under  
Remisaidpur Block

## A. For Road

1. Damage location / Chainage :- 26. 369826, 85. 436973

2. Damage Length :- 0.133 km

3. Nature of Damage ( Length Wise)

(i) Breach :- 0.133 km

(ii) Crust Damage :-

(iii) Only Flank Damage

Whether Traffic Fully / Partially obstructed :- Fully Obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick bats, Labbish

(ii) Equipment / Tools Being used in Restoration Work :- JCB, Tractor, Roller

(iii) Restored Length

In open Area :- 0.133 km

In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :-

## B. For Bridge (Size of Bridge / Culvert )

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage ( Pier/Abutment/  
Wing Wall/ Approach Road Damage ) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :-

(iii) Restored Length

Overall Grade of restoration Work ( Satisfactory/Unsatisfactory) :- Satisfactory

Signature of Inspector  
(Official Seal) Executive Engineer