

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Ruid, Jhanglarpur	
Name of Block/Road :- Madhaur, Basypate - Garhgawn	
A. For Road	
1. Damage Location/Chainage :- CH 4.1, 4.2, 4.3 k-m.	
2. Damage Length :- 73.50 m	
3. Nature of Damage (Length Wise)	(i) Breach :- 73.50 m
	(ii) Crust Damage :-
	(iii) Only Flank Damage :-
whether traffic fully/Partially obstructed :- Fully	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works :- JCB and Tractor	
(iii) Restored Length	In open Area :- open Area
	In habitation Area :- N/A
(iv) If Restoration work done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttment/Wing Wall/Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works :-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-	

Ques
14/11/24
J-E

Executive Engineer
Signature of Inspector
Office Seal
Muzaffarnagar