


## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Rised, Jhagharpur	
Name of Block/Road :- Madhepur / Mahender to Raha.	
<b>A. For Road</b>	
1. Damage Location/Chainage :- ch - 1.68 KM, 2.95 KM	
2. Damage Length :- 12m.	
3. Nature of Damage (Length Wise)	(i) Breach :- 12m.
	(ii) Crust Damage :-
	(iii) Only Flank Damage :-
whether traffic fully/Partially obstructed :- fully.	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- Bricks bats.	
(ii) Equipment/Tools Being Used in Restoration Works :- JCB and trowels.	
(iii) Restored Length	In open Area :- open
	In habitation Area :- N.A
(iv) If Restoration work done in habitation Area give Reason :- N.A	
<b>B. For Bridge (Size of Bridge/Culvert)</b>	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abutment/Wing Wall/Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works :-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-	

Q. No. 14/11/24  
J.E.

  
**Executive Engineer**  
 Rural Works Department  
 Signature of Inspector  
 Works Division, Jaynagar  
 (Official Seal)