



## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :-		RKID, Jharkhand	
Name of Block/Road :-		Madhepur / 631 - Kursum to Basipali	
<b>A. For Road</b>			
1. Damage Location/Chainage :-		5.70 km, 6.60 km, 6.80 km, 7.10 km	
2. Damage Length :-		87.90 m	
3. Nature of Damage (Length Wise)	(i) Breach :-	87.90 m.	
	(ii) Crust Damage :-		
	(iii) Only Flank Damage :-		
whether traffic fully/Partially obstructed :-		Fully	
4. Details of Restoration :-			
(i) Material Being Used in Restoration :-		Brick ball	
(ii) Equipment/Tools Being Used in Restoration Works :-		JCB & Grader	
(iii) Restored Length	In open Area :-	open	
	In habitation Area :-		
(iv) If Restoration work done in habitation Area give Reason :-			
<b>B. For Bridge (Size of Bridge/Culvert)</b>			
(1) Damage Location/Chainage :-			
(2) No. of Span Damage :-			
(3) Length of Span :-			
(4) Nature of Damage (Pier/Abutment/Wing Wall/Approach Road Damage) :-			
(5) Details of Restoration :-			
(i) Material Being Used in Restoration :-			
(ii) Equipment/Tools Being Used in Restoration Works :-			
(iii) Restored Length :-			
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-			

  
 Inspector  
 J.E.

  
 Executive Engineer  
 Signature of Department  
 (Official Seal)  
 Works Division, Jaynagar