

## Inspection Report for Flood Damage work

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road

Katra / Gram Bhawanipur Ajit Paswan ke Ghar to Mahudalit Tola Barhamasthan Tak.

A For Road 0.

1 Damage Location/Chainage 0.4 Km

2 Damage Length 0.080 Km

3 Nature of Damage Damage due to flood.

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length 0.080 Km

Bricks bats and local Sand  
Tractor, JCB, Dumper Roller  
Spreading of Bricks bats and  
local Sand then Compacting Surfer.

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

*[Signature]*  
12/11/24

*[Signature]*  
12/11/24  
AE

Signature (Name of Inspector)

*[Signature]*  
12/11/24

Executive Engineer  
RWD Works Division  
Muzaffarpur East-1