

# Inspection Report for Flood Damage work

Date

Muzaffarpur East-2

1 Name of PIUS

2 Name of Block/Road Aurai/PMHSY Road Sarbachiya haziya Tola to  
Prathmik Vidhalya Tak

A For Road

1 Damage Location/Chainage 0.4 Km

2 Damage Length 0.040 Km

3 Nature of Damage Damage due to Flood

4 Details of Restoration Works

Brick balls and local Sand

i material Being used in Restoration Works

Tractor JCB, Dumper Roller

ii Equipments/Tools being used in Restoration Works

Spreading of Bricks balls and  
local sand and then Compacting  
the Surface.

iii Procedure Taken up in Restoration Works

iv Restored length 0.039 Km.

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

Signature (Name of Inspector)

Executive Engineer  
RWD Works Division  
Muzaffarpur East-1