

Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-1

2 Name of Block/Road *AURAT/Ram Hirday shah house Madarsha to Benipur Naya Bashi Tak*

A For Road *0.8 and 0.12 Km*

1 Damage Location/Chainage

2 Damage Length *0.010 Km*

3 Nature of Damage *Damage due to flood*

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length *0.054 Km*

*Brick bats and Local Sand
Tractor, JCB, Dumper, Roller
Spreading of Bricks bats and
local Sand and then Compacting the
Surface.*

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

Shamir
12/11/24

Shamir
13/11/24
AE

Signature (Name of Inspector)

Y. P. @
13/11/24
Executive Engineer
RWD Works Division
Muzaffarpur East-1