INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- R.W.D. Sup. 1	
Name of PIUs:- R.W.D, Sypay Name of Block/Road:- Kishaupur/Baoraha to Kamaldaha A. For Road	
A For Pond	
1. Damage Location/Chainage:- ALCH-DE-LOCAL	
2. Damage Length: 53.10m	
3. Nature of Damage (Length Wise) (i) Breach: fully breached	
(ii) Crust Damage:-	
(iii) Only Flank Damage:-	
whether traffic fully/Partially obstructed:- Fully obstructed	
4. Details of Restoration:	,
(i) Material Being Used in Restoration:- Brick-bats.	
(ii) Equipment/Tools Being Used in Restaration Works	
(ii) Equipment/Tools Being Used in Restoration Works: - J.C.B. Tractor etc.	
In open Area: 53.10 m	
In habitation Area:-	
(iv) If Restoration work done in habitation Area give Reason:-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttment/	
Wing Wall/Approach Road Damage):-	
(5) Details of Restoration:-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works:-	

14 11/2024 A.E.

(Official Seal) Executive Engineer
Rural Works Department
Works Division Udakishunganj