

Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road Aurai/LO 84 - Pmsy to Berauna Musahzi Tola.

✓ A For Road

1 Damage Location/Chainage 0.800 Km

2 Damage Length 0.010 Km

3 Nature of Damage Damage due to flood.

4 Details of Restoration Works Brick bats and local Sand
Tractor, JCB, Dumper, Roller
i material Being used in Restoration Works Spreading of Bricks bats and local
ii Equipments/Tools being used in Restoration Works Sand and then Compacting the Surface.
iii Procedure Taken up in Restoration Works
iv Restored length 0.08 Km.

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE
12/11/24

Signature
12/11/24
AE

Signature (Name of Inspector)
13/11/24
Executive Engineer
RWD Works Division
Muzaffarpur East-1