

Inspection Report for Flood Damage work

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road *Katra/T01-Bagani to lakhanpur Road (OPRI)*

✓ A For Road

1 Damage Location/Chainage *0.600 Km*

2 Damage Length *0.100 Km*

3 Nature of Damage *Damage due to flood*

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length *0.081 Km.*

*Brick bats and local Sand
Tractors, JCB, Dumper Roller
Spreading of Bricks bats and local
Sand and then Compacting the Surface.*

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

Shamir
12/11/24

AE
12/11/24

Signature (Name of Inspector)

Y. A.
13/11/24
Executive Engineer
RWD Works Division
Muzaffarpur East-1