

## Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road

AURAI / SHIVDIYAL RAI KHET TO MIDDLE SCHOOL  
MUSHARI TOLA HVE AMBEDKAR NAGAR.

✓ A For Road

1 Damage Location/Chainage

0.440 km

2 Damage Length

— 0.050 km

3 Nature of Damage

— DAMAGE DUE TO FLOOD.

4 Details of Restoration Works

i material Being used in Restoration Works

— BRICK BATS AND LOCAL SAND.

ii Equipments/Tools being used in Restoration Works

— TRACTOR, JCB, ROLLER, DUMPER.

iii Procedure Taken up in Restoration Works

— SPREADING OF BRICK BATS AND

iv Restored length

LOCAL SAND AND THEN COMPACTING THE  
— 0.048 km SURFACE

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

*Shamir*  
13/11/24

*Shamir*  
13/11/24  
AE

Signature (Name of Inspector)

*Y. P. Singh*  
13/11/24  
Executive Engineer  
RWD Works Division  
Muzaffarpur East-1