

## Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road

Aurai/Suresh Pashwan to Sri Ram Vasthalya Aurai Tark.

A For Road

1 Damage Location/Chainage 1.5 Km

2 Damage Length 0.100

3 Nature of Damage

Damage due to flood.

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length 0.012 Km

Brick bats and local Sand  
Tractor, JCB, Dumper, Roller  
Spreading of Brick bats and local  
Sand and then Compacting the Surface.

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

Signature  
13/11/24  
AE

Signature (Name of Inspector)

12/11/24  
Executive Engineer  
RWD Works Division  
Muzaffarpur East-1