

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Sri Avinash Kumar, EE RWD Sitamarhi

Name of Block / Road :- Sahiyara Jhama Kaitahi to Kharbandi
Jola under Bathnaha Block

A. For Road

1. Damage location / Chainage :- at chainage :- 1.0 KM, lat. 26.710225 long :- 85.4599

2. Damage Length :- 19.00 m

3. Nature of Damage (Length Wise)

(i) Breach :- P 19.00 m

(ii) Crust Damage :-

(iii) Only Flank Damage

Whether Traffic Fully / Partially obstructed :- partially obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick Bata, Rubbish

(ii) Equipment / Tools Being used in Restoration Work :- JCB, Tractor

(iii) Restored Length

In open Area :- ✓ 19.00 m

In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :- NA

B. For Bridge (Size of Bridge / Culvert)

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/ Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :-

(iii) Restored Length

Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :-

Signature of Inspector
(Official Seal)