INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- Rwo,	They herpur.
Name of Block/Road :- Madlep	They berpur. ir/Pmary Sedele to Navtoliye
A. For Road	
1. Damage Location/Chainage:- o m	
2. Damage Length: 70.80 m	
3. Nature of Damage (Length Wise)	(i) Breach: fosom.
	(ii) Crust Damage:-
	(iii) Only Flank Damage :-
whether traffic fully/Partially obstructed:- Fully	
4. Details of Restoration:-	
(i) Material Being Used in Restoration: Tess & Frecher Brick Vole	
(ii) Equipment/Tools Being Used in Restoration Works: - JCB9 Tredus	
(iii) Restored Length	In open Area:- Cp on
	In habitation Area:-
(iv) If Restoration work done in habitation Area give Reason:-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage:-	
(2) No. of Span Damage:-	
(3) Length of Span:-	
(4) Nature of Damage (Pier/Abuttment/	
Wing Wall/Approach Road Damage):-	
(5) Details of Restoration:-	
(i) Material Being Used in Restoration	
(ii) Equipment/Tools Being Used in I	Restoration Works :-
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):-	
	HARUY

MC/OIME

Executives Engines:
Signanue of Inspector:
Rural Works Department
Works Division, Jaynagar