



INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :-		RWID, Jhanghalpur	
Name of Block/Road :-		Madhepur / Nakta Tule to Mahaur Pmaly Road.	
A. For Road			
1. Damage Location/Chainage :-			
2. Damage Length :- 43.30 m			
3. Nature of Damage (Length Wise)		(i) Breach :- 43.30 m.	
		(ii) Crust Damage :-	
		(iii) Only Flank Damage :-	
whether traffic fully/Partially obstructed :- Fully			
4. Details of Restoration :-			
(i) Material Being Used in Restoration :- Brck Vatr			
(ii) Equipment/Tools Being Used in Restoration Works :- JCB & Tractors			
(iii) Restored Length		In open Area :- open	
		In habitation Area :- N/A	
(iv) If Restoration work done in habitation Area give Reason :-			
B. For Bridge (Size of Bridge/Culvert)			
(1) Damage Location/Chainage :-			
(2) No. of Span Damage :-			
(3) Length of Span :-			
(4) Nature of Damage (Pier/Abutment/Wing Wall/Approach Road Damage) :-			
(5) Details of Restoration :-			
(i) Material Being Used in Restoration :-			
(ii) Equipment/Tools Being Used in Restoration Works :-			
(iii) Restored Length :-			
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-			


 14/11/24
 J.E.


 Executive Engineer
 Road Works Department
 Signature of Inspector
 Works Division, Jhanghalpur
 (Official Seal)