

Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road

Katwa/ Madhopur Mushar tola to primary Road

✓ A For Road

48

1 Damage Location/Chainage 0.800 Km

2 Damage Length 0.045 Km

3 Nature of Damage Damage due to flood.

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

0.0448 Km.

Brick bats and local Sand
Tractor, JCB, Dumper, Roller
Spreading of Brick bats and local
Sand and then Compacting the Surface

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

8/11/24
13/11/24

Signature
13/11/24
AE

Signature (Name of Inspector)

4/11/24
13/11/24
Executive Engineer
RWD Works Division
Muzaffarpur East-1