

## Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road - AVRAT / BHAIRO ASTHAN (TERA) MOD SE  
BASATAPUR HOTE HUE MURAAHA PATH

A For Road

1 Damage Location/Chainage 0.700km

2 Damage Length - 0.100 km

3 Nature of Damage - DAMAGE DUE TO FLOOD

4 Details of Restoration Works

i material Being used in Restoration Works - BRICKS BATS AND LOCAL SAND  
ii Equipments/Tools being used in Restoration Works - TRACTOR, JCB, ROLLER, DUMPER  
iii Procedure Taken up in Restoration Works - SPREADING OF BRICK BATS AND  
iv Restored length 0.096km LOCAL SAND AND THEN COMPACTING THE SURFACE

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

Signature (Name of Inspector)

EXECUTIVE ENGINEER  
RWD Works Division  
Muzaffarpur East-1