

Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road AVRAI / LOS3 - AMNAUR TOY TO BAHVARA

☒ A For Road

1 Damage Location/Chainage 0.500km & 1.00km.

2 Damage Length — 0.035km

3 Nature of Damage — DAMAGE DUE TO FLOOD.

4 Details of Restoration Works

i material Being used in Restoration Works — BRICKS BATS AND LOCAL SAND ^{HUME PIPE}

ii Equipments/Tools being used in Restoration Works — TRACTOR, JCB, ROLLER, DUMPER.

iii Procedure Taken up in Restoration Works — SPREADING OF BRICK BATS AND

iv Restored length — 0.035km LOCAL SAND AND THEN COMPACTING THE SURFACE

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

Signature (Name of Inspector)

Executive Engineer
RWD Works Division
Muzaffarpur East-1