

Inspection Report for Flood Damage work

Date

- 1 Name of PIUS Muzaffarpur East-2
- 2 Name of Block/Road Aurai/Pupari Janewali Balia More se High School
hote hue to Mehsaul Suman Tak

A For Road

- 1 Damage Location/Chainage 2.3 Km.
- 2 Damage Length 0.040 Km
- 3 Nature of Damage Damage due to flood
- 4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length 0.0370 Km

Bricks balls and local Sands
Tractor, JCB, Dumper, Roller
Spreading of Brick and Local
Sand and then Compacting the Surface.

B For Bridge

- 1 Damage Location/Chainage
- 2 Damage Length
- 3 Nature of Damage
- 4 Details of Restoration Works
- i material Being used in Restoration Works
- ii Equipments/Tools being used in Restoration Works
- iii Procedure Taken up in Restoration Works
- iv Restored length

Signature of JE/AE/EE
Sham
12/11/24

Signature
13/11/24
AE

Signature (Name of Inspector)
Executive Engineer
RWD Works Division
Muzaffarpur East-1
13/11/24