

Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road - BOCHHAHA/TOI - SAHILA RAMPUR TO NARMA

✓ A For Road

1 Damage Location/Chainage - 2.8 km

2 Damage Length - 0.060 km

3 Nature of Damage - DAMAGE DUE TO FLOOD

4 Details of Restoration Works

i material Being used in Restoration Works - BRICK BATS AND LOCAL SAND AND SAND BAGS.

ii Equipments/Tools being used in Restoration Works - TRACTOR, JCB, DUMPER, ROLLER

iii Procedure Taken up in Restoration Works - SPREADING OF BRICK BATS AND LOCAL

iv Restored length - 0.054 km SAND AND THEN COMPACTING THE SURFACE.

B X For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

Signature (Name of Inspector)

Executive Engineer
RWD Works Division
Muzaffarpur East-1