

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE, RWD, Works Division, Beland	
Name of Block / Road :- Sitamachi Jila ke beland Prakhend ke Rupauli panchayat ke gram saili me baikunth Singh ke ghar se sundarpur ghat tak gram in sadak ka nirman	
A. For Road	
Damage location / Chainage :- 0.033 km 26.463249, 85.383912	
Damage Length :- 0.033 km	
Nature of Damage (Length Wise)	(i) Breach :- 0.033 km
	(ii) Crust Damage :-
	(iii) Only Flank Damage
Whether Traffic Fully / Partially obstructed :- Fully obstructed	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- Brick Bats, Rabbish	
(ii) Equipment / Tools Being used in Restoration Work :- JCB, Tractor, Roller	
(iii) Restored Length	In open Area :- 0.033 km
	In Habitation Area :-
(iv) If Restoration Work Done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge / Culvert)	
(1) Damage Location / Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttment/ Wing Wall/ Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment / Tools Being used in Restoration Work :-	
(iii) Restored Length	
Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :- Satisfactory	

Signature of Inspector
(Executive Engineer)
Rural Works Department
Works Division, Sheohar