

Inspection Report for Flood Damage work

Date

1 Name of PIUS

Muzaffarpur East-2

2 Name of Block/Road Aurai/ NH-77 se Gopalpur Sarachiya Bandh tak

A For Road

1 Damage Location/Chainage 0.4 Km, 0.8 Km, 1.5 Km

2 Damage Length 0.100 Km

3 Nature of Damage Damage due to flood

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length 215.5 m.

Brick bats and local Sand
Tractor, JCB, Dumper, Roller
Spreading of Brick bats and Local
Sand and then Compacting the Surface

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

Signature (Name of Inspector)

Executive Engineer
RWD Works Division
Muzaffarpur East-2