

Inspection Report for Flood Damage work

Date

Muzaffarpur East-2

1 Name of PIUS

2 Name of Block/Road - GAIGHAT / KATA PRAUCHA TO B. SITAL

A For Road

1 Damage Location/Chainage - 0M

2 Damage Length - 0.150 km

3 Nature of Damage - Damage due to flood.

4 Details of Restoration Works

i material Being used in Restoration Works - BRICK BATS & LOCAL SAND

ii Equipments/Tools being used in Restoration Works - ROLLER, DUMPER, TRACTOR.

iii Procedure Taken up in Restoration Works - Filling of Brick Bats then rolling, then

iv Restored length - 0.122 km Spreading of L. Sand then Compacting the surface.

B For Bridge X

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i material Being used in Restoration Works

ii Equipments/Tools being used in Restoration Works

iii Procedure Taken up in Restoration Works

iv Restored length

Signature of JE/AE/EE

Signature (Name of Inspector)
Executive Engineer
RWD Works Division
Muzaffarpur East-1